

From: "Colacurcio, Joe" <Joe.Colacurcio@nielsen.com>.

Sent: 8/21/2008 4:58 PM.

To: [-] <greg_bryan@toyota.com>; <gordon_rush@toyota.com>.

Cc: [-] "Randy_Wagner@toyota.com" <'Randy_Wagner@toyota.com'>; "Jeff_Northrup@toyota.com" <'Jeff_Northrup@toyota.com'>; "craig_erickson@toyota.com" <'craig_erickson@toyota.com'>; "matt_allen@toyota.com" <'matt_allen@toyota.com'>; "brian_lyons@toyota.com" <'brian_lyons@toyota.com'>; "Randy_Reida@toyota.com" <'Randy_Reida@toyota.com'>; "Howard_Abrahams@toyota.com" <'Howard_Abrahams@toyota.com'>; "Russell_Suzuki@toyota.com" <'Russell_Suzuki@toyota.com'>; "Mike_Robinson@toyota.com" <'Mike_Robinson@toyota.com'>; "Gary_Heine@toyota.com" <'Gary_Heine@toyota.com'>; "Bob_Nagai@toyota.com" <'Bob_Nagai@toyota.com'>; "Tom_Krembs@toyota.com" <'Tom_Krembs@toyota.com'>; "michael_jarboe@toyota.com" <'michael_jarboe@toyota.com'>; <Tom_Kim@toyota.com>; <Charles_Lee@Toyota.com>; <glen_fujita@toyota.com>; <ruben_nieto@toyota.com>; "Enzweiler, Julie" <Julie.Enzweiler@nielsen.com>; "Stephenson, Bill" <Bill.Stephenson@nielsen.com>; "Black, Larry" <Larry.Black@nielsen.com>; "Patak, Elizabeth" <Elizabeth.Patak@nielsen.com>; "Hamm, Scott" <Scott.Hamm@nielsen.com>.

Bcc: [-] .

Subject: RE: Toyota PQSS Executive Summary through August 16, 2008.

Hello,

Attached please find the Toyota Quality Executive Summary report reflecting data from August 3rd, 2008 – August 16th, 2008. The reporting site (<http://toyota.reports.buzzmetrics.com/main.asp>) has also been updated with the latest information.

Toyota

4Runner Current Generation

Cargo Area "Knocking Sound"/Lemon Law
Creaking Driver's Seat
Rattling Noise

Avalon Current Generation

Engine Ticking Noise When Cold
Dashboard Rattle

Camry Current Generation

4-cylinder Hesitation and Vibrations
V6 Transmission Flares
Inconsistent Starts
Paint Chips
Dark Power Steering Fluid

Camry Hybrid Overall

Interior Rattles

Corolla Current Generation

General Vehicle Dislikes/Issues
Stereo Volume Problem
Possible Transmission Failure

Corolla Previous Generation

Transmission Problems
Various Vehicle Noises

Starting Problems
Engine Vibration

Highlander Current Generation

Potential Front Suspension Issue

Highlander Hybrid Overall

Steering Wheel Noise
Electrical Problems

Matrix Previous Generation

Acceleration/Deceleration on Highway
Possible Issue with Transmission Fluid
Rough Shifting

Prius Current Generation

Potential Brake Failures
MFD and NAV Failures
Headlight Problems
Hybrid System Problems

RAV4 Current Generation

Engine Hesitation/Stumble
Idle Vibrations
"Unbearable" Engine Noise

Sienna Current Generation

Power Door Problems
Door Weld Questions
Moisture Problem/Bad Body Welds
Alloy Wheels Peeling
Erratic Cruise Control
A/C Failure

Sienna Previous Generation

Engine Fire

Tacoma Current Generation

"Lurch" Issue
Ride Vibrations
Leaf Springs TSB
Paint Problems

Tacoma Previous Generation

Frame Rust/Buy-Back

Tundra Current Generation

Ride Vibrations
Rusted Chrome Bumpers
Buyer's Remorse (Needs new driveshaft)

Yaris Overall

Tires Causing "Growl" Sounds
Paint Peeling

Lexus

Lexus ES 350 Overall

Paint Issues
Throttle "Cut Back"

Lexus GS 300 Overall

Wind Noise From Moonroof

Lexus GS 350 Overall

Constant "Squeaking" Under 55 MPH

Lexus GS 460 Overall

TPMS with Run-Flat Tires

Lexus LS 430 Overall

Fuel Pump Issue

Lexus LX 570 Overall

Vibrations

Lexus RX 400h Overall

A/C Stops Blowing Cold Air When Stopped

Scion

Scion tC Overall

Manual Transmission Grinds

Scion xB Previous Generation

Cracked Windshield

Please feel free to contact us if you have any questions.
Thanks,

Joe Colacurcio

Senior Analyst, Automotive

Nielsen Online

The Nielsen Company

50 West RiverCenter Blvd.

Third Floor

Covington, KY41011

859.905.4936 voice

610.462.3048 mobile

joe.colacurcio@nielsen.com

www.nielsen-online.com